Scope of	Work for Prop	erty Located	l at:		<u>2567</u>	-69 Nor	th 38	th Street		
	Property is:	Single Family		Duplex	X	Other				
Date:	11/12/2010									
ake no respo	minimum requirement consibility for problems of the by private lenders, in	discovered after th	e insp	ection date	, or for o	missions tl	hrough	error or oversig		
Exterior	Condition Repo	ort								
Location Site	Required Work Landscaping	K n/a	Х	Yes	Note/ Self He	Commen	nts		\$	Cost
	Steps/Handrails	n/a	X	Yes					\$	
	Service walks	n/a	X	Yes					\$	
	Fencing	n/a	X	Yes					\$	
	Parking	n/a	Χ	Yes					\$	
	Retaining walls	n/a	Χ	Yes					\$	
	Other	n/a	Χ	Yes					\$	
	Other	n/a	Χ	Yes					\$	
Garage	Shingles: repair	n/a	Х	Yes					\$	
	Shingles: Roof ove	r existing n/a	Χ	Yes					\$	
	Shingles:Tear off 8	re-roof n/a	Х	Yes					\$	
	Gutters/downspout	s n/a	Х	Yes					\$	
	Flashing	n/a	Х	Yes					\$	
	Eaves	n/a	Χ	Yes					\$	
	Siding	n/a	X	Yes					\$	
	Doors	n/a	X	Yes					\$	
	Windows	n/a	X	Yes					\$	
	Slab	n/a	X	Yes					\$	
	Paint	n/a	X	Yes					\$	
	Electrical	n/a	X	Yes					\$	
	Other	n/a		Yes					\$	
Porches	Roof	n/a	Х	Yes					\$	
	Deck-upper	n/a	X	Yes					\$	
	Decklower	n/a	X	Yes					\$	
	Steps/handrails	n/a	X	Yes					\$	
	Ceiling	n/a	X	Yes					 \$	
	Guardrails	n/a	X	Yes					\$	
	Structural	n/a	X	Yes					\$	
	Paint	n/a	V	Yes 🗍					 \$	

n/a Yes

Other

\$

## House

Chimney	n/a	Yes X	Areas of roof shingles damaged	\$ 1,600.00
Shingles: repair	n/a X	Yes 🗌		\$
Shingles: Roof over existing	n/a X	Yes 🗌		\$ 
Shingles:Tear off & re-roof	n/a X	Yes 🗌		\$ 
Gutters/downspouts	n/a X	Yes 🗌		\$ 
Flashing	n/a X	Yes 🗌		\$ 
Eaves	n/a	Yes X	Wood trim peeling paint/soffit damaged	\$ 1,150.00
Siding	n/a	Yes X	Wood siding peeling paint	\$ 2,000.00
Storm Doors	n/a X	Yes 🗌		\$ 
Prime ("main") Doors	n/a X	Yes 🗌		\$ 
Storm Windows	n/a X	Yes 🗌		\$ 
Prime ("main") Windows	n/a X	Yes 🗌		\$ 
Paint	n/a X	Yes 🗌		\$ 
Foundation	n/a X	Yes 🗌		\$
Electrical	n/a X	Yes 🗌		\$
Other	n/a	Yes		\$
Other	n/a	Yes		\$
Other	n/a	Yes		\$
Other	n/a	Yes 🗌		\$

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

4,750.00

Interior Co	ondition Report			<u></u>	
	Unit: Entire unit (single family) Upper unit of duplex	X		Lower unit of duplex X Other	
Mechanical Heating	Required Work				
rieating	Repair/replace boiler	n/a X	Yes		\$
	Repair radiation	n/a X	Yes		\$
	Repair/replace furnace	n/a	Yes X	Replace two furnaces	\$ 8,000.00
	Repair ductwork	n/a X	Yes	]	\$ •
	Replace thermostat	n/a X	Yes		\$
	Repair/replace grilles	n/a X	Yes		\$
	Tune boiler/furn. insp ht exchang		Yes		\$
Electrical	Repair/replace receptacles	n/a X	Yes		\$
	Repair/replace switches	n/a X	Yes		\$
	Repair/replace fixtures	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Upgrade service	n/a X	Yes		\$
	Other	n/a	Yes		\$
	Other	n/a	Yes		\$
Plumbing	Repair/replace kitchen sink	n/a X	Yes		\$
	Repair/replace kitchen sink fauce	etn/a X	Yes		\$
	Repair/replace tub	n/a X	Yes		\$ 
	Repair/replace tub faucet	n/a X	Yes		\$
	Repair/replace toilet	n/a X	Yes		\$
	Repair/replace lavatory	n/a X	Yes		\$
	Repair/replace lavatory faucet	n/a X	Yes		\$
	Repair/replace wash tub	n/a X	Yes		\$
	Repair/replace wash tub faucet	n/a X	Yes		\$
	Unclog piping:	n/a X	Yes		\$
	Repair drain/waste/vent piping	n/a X	Yes		\$
	Repair water piping	n/a X	Yes		\$
	Repair/replace water heater	n/a	Yes X	Replace water heater	\$ 650.00
	Other	n/a	Yes		\$

n/a Yes

Other

\$

				Total Exterior and Interior Cost:*	<u> </u>	16,150.00
				Interior: Estimated Cost:	\$	11,400.00
		n/a	Yes 🗌		\$	
		n/a	Yes 🗌		\$	
		n/a	Yes 🗌		\$	
		n/a	Yes X	Could not access 2nd floor unit	\$	
Other	Repair defective	n/a	Yes X	Several rooms need new coverings	\$	1,200.00
Floors	D : 1 ( #	, [	v		•	4 000 00
Stairs	Repair defective	n/a 🗓	Yes 🗌		\$	
	Repair/replace defective	n/a X	Yes 🗌		\$	
Handrails	Install smoke alarm: 2nd flr.	n/a X	Yes	Self Help	\$	
	Install smoke alarm: 1st flr.	n/a X	Yes	Self Help	\$	
	Install smoke alarm:bsmt.	n/a X	Yes	Self Help	\$	
Fire Safety						
Paint	Repair or repl. @ defective	n/a	Yes X	Several need fresh paint	\$	500.00
	Repair or repl. @ defective	n/a	Yes X	Several areas water damaged	\$	800.00
Walls/Ceilin		7.1. <u>X</u>			· · · · · · · · · · · · · · · · · · ·	
	Repair or repl. locks/latches	n/a X	Yes	Self Help	\$	
Doors	Repair or replace doors	n/a 💢	Yes 🗍		\$	
_	Repair or replace sash	n/a χ	Yes		\$	
	Replace broken glass	n/a	Yes X	Several cracked glass	\$	250.00
Windows						

## Prepared by: JEFF MOSER, ADVANTAGE HOME INSPECTION SERVICES Date: 11/14/2010

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.